L Number	Hits	Search Text	DB	Time stamp
1	1	6541886.pn.	USPAT	2003/08/09 19:38
2	4	("4381465" | "5811903" | "6046519" | "6255749").PN.	USPAT	2003/08/09 19:37
3	0	6541886.URPN.	USPAT	2003/08/09 19:38
4	664	310/91.ccls. and stator	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 19:56
5	157	310/91.ccls. and stator and rotor and (rotor adj shaft)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 19:39
6	497	310/91.ccls. and stator and motor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 20:43
7	747	310/89.ccls. and stator and motor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 20:43
8	613	310/89.ccls. and stator and motor and shaft	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 20:44
9	567	310/89.ccls. and stator and motor and shaft and rotor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 20:45
10	567	310/89.ccls. and stator and motor and shaft and rotor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 20:45
11	0	20010035693.URPN.	USPAT	2003/08/09 20:52
12	1106	310/49r.ccls. and stator	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/08/09 21:08
13	605	310/71.ccls. and stator	USPAT	2003/08/09 21:09
14	400	310/258.ccls. and stator	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 21:10
15	267	310/258.ccls. and stator and motor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 21:17
16	3166	H02K005/00.ipc.	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 21:17
17	637	H02K005/00.ipc. and motor and stator and rotor	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 21:17
18	479	H02K005/00.ipc. and motor and stator and rotor and shaft	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 21:18
19	282	H02K005/00.ipc. and motor and stator and rotor and shaft and (coil or winding or bobbin)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 21:37

C:\APPS\east\workspaces\09865053.wsp

20	78	H02K037/04.ipc. and motor and stator and rotor and shaft and (coil or winding or bobbin)	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/08/09 21:37
-	1225	310/71.ccls.	USPAT	2002/05/23 11:53
-	0	310/$$.ccls. and stator near ((coil adj bobbin) same terminal) and windings	USPAT	2002/06/19 11:26
-	0	310/$$.ccls. and stator near ((coil adj bobbin) same terminal) and windings and (hub or case or housing or cover)	USPAT	2002/06/19 11:28
-	0	stator near ((coil adj bobbin) same terminal) and windings and (hub or case or housing or cover)	USPAT	2002/06/19 11:32
-	0	stator near ((coil adj bobbin) same terminal)	USPAT	2002/06/19 11:41
-	49	("4604587" "5319270" "5410201" "5644203" "5769069" "5786645" "5942823" "6031305" "4315329" "4460859" "4593216" "4763053" "5264769" "5528096" "5581519" "5583404" "5717297" "5734211" "6107708" "6155969" "6222684" "6222684" "4156821" "4263524" "4274150" "4302692" "4307311" "4321521" "4329606" "4334749" "4336471" "4347452" "4352036" "4352172" "4354145" "4361776" "4368990" "4373256" "4382691" "4395815" "4403174" "4404484" "4418307" "4426159" "4437769" "4441043" "4459520" "4460282" "4468579" "4486697").pn.	USPAT	2002/06/19 11:42

	50	("4490664"		USPAT	2002/06/19
		"4500825"			11:49
		"4507590"			
		"4510422"			
		"4511828"			
		"4521706"			
		"4531072"			
		"4532446"			
		"4535263"			
		"4538083"			
		"4541603"			
		"4564778"			
		"4564777"			
		"4564775"			
		"4568862"			
		"4573001"			
		"4577129"			
		"4581554"			
		"4588912"			
		"4607803"			
		"4617499"			
		"4633156"			
		"4755701"			
		"4762471"			
		"4769581"			
		"4793689"			
		"4803576"			
		"4805054"			
		"4820951"			
		"4823034"			
		"4831474"			
		"4839551"			
		"4839552"			
		"4845578"			
		"4855629"			
		"4866324"			
		"4874233"			
		"4874976"			
		"4874977"			
		"4888511"			
		"4897681"			
		"4912690"			
		"4922604"			
		"4947236"			
		"4952859"			
		"4973869"			
		"4998033"			
		"5008572"			
		"5070269"			
		"5036237").pn.			

—	50	("5194787" "5223760" "5233248" "5234192" "5245235" "5252876" "5264748" "5278470" "5283495" "5296981" "5304878" "5327064" "5334023" "5350960" "5355043" "5357162" "5396968" "5413469" "5414331" "5416395" "5446360" "5446514" "5460503" "5471384" "5493187" "5507424" "5521475" "5543700" "5578883" "5589751" "5600193" "5628951" "5631512" "5654597" "5675206" "5677587" "5677581" "5689746" "5689147" "5705864" "5714814" "5723933" "5729070" "5731927" "5754024" "5759128" "5760512" "5767601" "5784922" "5796204").pn.	USPAT	2002/06/19 11:54
—	1809	310/49r.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/06/19 18:53
—	1	5004941.pn.	USPAT	2002/06/22 15:34
—	1	6046519.pn.	USPAT	2002/06/22 15:34
—	1	5043613.pn.	USPAT	2002/06/22 15:35
—	1	5770900.pn.	USPAT	2002/06/22 15:35
—	224	310/257.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/06/22 15:39
—	25	"5121017"	USPAT	2003/07/30 17:41

-	0	"5121017.pn."	USPAT	2003/07/30 17:41
-	1	5121017.pn.	USPAT	2003/07/30 17:41
-	3	("3843946" | "4426158" | "5173628").PN.	USPAT	2003/07/30 18:28
-	553648	310/$.ccls. and stepping motor	USPAT	2003/07/31 12:24
-	1450	310/$.ccls. and (stepping adj motor)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/31 12:25
-	204	310/$.ccls. and (stepping adj motor)and (rotor adj shaft) and stator	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/31 12:56
-	0	20020140303.URPN.	USPAT	2003/07/31 12:27
-	0	eiji adj mayumi.in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/31 12:57
-	0	(eiji adj mayumi).in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/31 12:59
-	0	(eiji adj mayumi).in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/31 12:59
-	15	(eiji near mayumi).in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/31 12:59
-	4	("4381465" | "5811903" | "6046519" | "6255749").PN.	USPAT	2003/07/31 13:00
-	0	6541886.URPN.	USPAT	2003/07/31 13:02

C:\APPS\east\workspaces\09865053.wsp